

Pos.	Alte Bez.	Bez. 2	Kanal	Status	Neue Bez.	Bez. 2	Kanal	Status	Zubehör Bez.	Bez. 2	Kanal	Status
1.	Talento 891 03.59.0011.1	230VAC	1	Liq.	Talento 892 plus 03.76.0004.1	230VAC	2	Ja	/	/	/	/
2.	Talento 891 03.59.0028.1	12VAC/DC	1	Lieferbar	Talento 892 plus 03.76.0011.1	12VAC/DC	2	Nicht lieferbar	/	/	/	/
3.	Talento 892 03.59.0003.1	230VAC	2	Liq.	Talento 892 plus 03.76.0004.1	110/230VAC	2	Lieferbar	/	/	/	/
4.	/	/	/	/	Talento 892 plus 03.76.0011.1	24VAC/DC	2	Lieferbar	/	/	/	/
5.	Talento 893 03.59.0005.1	230VAC	3	Liq.	Talento 892 plus 03.76.0004.1	230VAC	2	Liq.	Talento CE plus 07.75.0003.1	230V	2	Lieferbar
6.	Talento 894 03.59.0007.1	230VAC	4	Liq.	Talento 892 plus 03.76.0004.1	230VAC	2	Liq.	Talento CE plus 07.75.0003.1	230V	2	Lieferbar
7.	Talento 991 03.59.0002.1	230VAC	1	Liq.	Talento 992 plus 03.76.0003.1	230VAC	2	Liq.	/	/	/	/
8.	Talento 992 03.59.0004.1	230VAC	2	Liq.	Talento 992 plus 03.76.0003.1	110/230VAC	2	Lieferbar	/	/	/	/
9.	Talento 993 03.59.0006.1	230VAC	3	Liq.	Talento 992 plus 03.76.0003.1	230VAC	2	Liq.	Talento CE plus 07.75.0003.1	230V	2	Lieferbar
10.	Talento 994 03.59.0008.1	230VAC	4	Liq.	Talento 992 plus 03.76.0004.1	230VAC	2	Lieferbar	Talento CE plus 07.75.0003.1	230V	2	Lieferbar
11.	Talento 994 03.59.0009.1	110VAC	4	Liq.	/	/	/	Liq.	/	/	/	/
12.	Talento 994 03.59.0010.1	24VAC/DC	4	Lieferbar	/	/	/	Lieferbar	/	/	/	/
13.	/	/	/	/	Talento LAN Plus 07.75.0003.1	230VAC	/	Lieferbar	/	/	/	/
14.	Set Talento Taxxi 07.01.0029.1	Tal. 891 Tal. 994	/	Liq.	Set Talento Taxxi Plus 07.75.0012.1	Tal. 892+ Tal. 992+	/	Lieferbar	/	/	/	/
15.	Talento Taxxi 07.01.0030.1	Tal. 891 Tal. 994	/	Liq.	Talento Taxxi Plus 07.75.0011.1	Tal. 892+ Tal. 992+	/	Lieferbar	/	/	/	/